# Weathertzenon Assistance Program

## Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

*Work Order Name:* WO/15015SE-3140/1

Work Order Type: Weatherization

**Audit Name:** 15015SE-3140Audit (11)

#### **CLIENT INFORMATION**

Client Name: Address:

Client ID: 15015SE-3140 Whitwell, TN 37397

Alt. Client ID: Marion

#### **AGENCY INFORMATION**

Agency: Southeast Tennessee Resource Agency Agency Phone: 423-9492 x191

**Address:** 312 Resource Rd **Fax:** (423) 949-4023

Dunlap, TN 37327 *Email Address:* 

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

1990's site built home.

### Measures

	Measure 1 F	Replace attic access panel			Componer	nts			Inspected
Comment				Estimated	1	Actual			
#	Material / Labor	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Replace a 2'x2' attic access panel	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 2 D	OWH Tank Insulation			Componer	nts			Inspected
	<b>Comment</b> 40 gallon water heater.								
	ommone to g	anon water meatern			Estimated	1	Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equ	uip DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Tank Insulation	Each	1					
3	Other	DHW Tank Insulation	Each	1					
C	Other Detail						_		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:						_	L	

Report Run On: 4/16/2010

Measure 3 DW	H Pipe Insulation			Componen	ts			Inspected		
<b>Comment</b> 10' of 1	" diameter insulation wrap									
				Estimated	·	Actual				
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	<b>Unit Cost</b>	Total		
1 Insulation	DHW Pipe Insulation	Each	1							
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.									
2 Labor	DHW Pipe Insulation	Each	1							
3 Other	DHW Pipe Insulation	Each	1							
Other Detail										
			Measur	e Sub Total:			Sub Total:			
				0	1- D4			Inspected		
	or Ins. R-19		Components B1							
Comment				Estimated		Actual				
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total		
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1023							
Other Detail										
			Measur	e Sub Total:			Sub Total:			
Field Notes:										

Report Run On: 4/16/2010

	<b>Measure 5</b> Fix I	mproper Venting (Cloth	nes Dryer	)	Componen	ts			Inspected
C	protrudir is 15 fee	ents installed with dampe ng through pipe. Must be et. No changes allowed. rization Materials and So	vented to Refer to A	outsid	le of home. I nent A- Stan	Maximum	n length		
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Dryer Vent w/ Metal Piping (upto 15' in length)	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Each	1					
(	Other Detail								
				Measur	e Sub Total:		]	Sub Total:	
	Field Notes:								

Report Run On: 4/16/2010

Inspected

<u>-</u>	or Barrier Needed ement/CrawIspace)		Components					
walls an earth. M	6 mil poly. Must be insta d support piers. Must be ust be secured at all sea rization Materials and So	securely ms. Refe	fastene r to Atta	ed. Must be achment A-S	cleated c	lown to		
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	1125					
2 Labor	Labor	Each	1125					
Other Detail								
			Measure	e Sub Total:		]	Sub Total:	
Field Notes:								
		Work O	rder Grai	nd Total:		Gran	d Total:	

Report Run On: 4/16/2010

Inspected